

Product: Logic controller “homeLYnk”

Reference number: LSS100100

<i>Date of release</i>	<i>HWx.y or SWx.y version</i>	<i>Description of change to previous version</i>	<i>Linked documents</i>
2013-6-25	HW-1.0 SW-1.0	First release after validation	2013.06.25-hl.img
2013-6-25_A	HW-1.0 SW-1.1	New kernel for RS-485, Serial 3161XXX only	2013.06.25_A-hl.img
2014-01-29	HW-1.1*	New isolators & DC/DC convertor	Homelynk_EMC_test.pdf 194300-012-2014.pdf 194300-010-2014_AJ.pdf 14WG005.pdf
2014-02-25	SW-1.2.0	New fuctions, BACnet Server, etc.	FW1_2_0-hl.img
2014-05-07	SW-1.2.1	New functions, bug fixes, etc	FW1_2_1-hl.img
2015-02-27	SW-1.3	See <i>Change_Log_spaceLYnk SW V1.1 & homeLYnk SW V1.3.docx</i>	homelynk-1.3.0.img AR1740_EdC_User_Guide_h omeLYnk_EN.pdf
2015-05-06	HW-1.2	Upgrade of BCU TPUART2 from version 5.2 to version 5.3; solving "TP disconnected" issue, RN-2015-W23	
2015-05-18	SW-1.3.1	See <i>Change_Log_spaceLYnk SW V1.1.1 & homeLYnk SW V1.3.1.docx</i>	homelynk-1.3.1.img
2016-04-20	SW-1.5.0	See <i>Change_Log_spaceLYnk SW V1.2.0 & homeLYnk SW V1.5.0.pdf</i>	homeLYnk-1.5.0.img
2016-07-22	SW-1.5.1	See <i>Change_Log_spaceLYnk SW V1.2.1 & homeLYnk SW V1.5.1.pdf</i>	homeLYnk-1.5.1.img
2016-10-21	HW-1.3*	Upgrade of PCB. Remove 10k resistor. Add capacitor 220n; solving “Failed start-ups of hL/sL” issue	Bill of Materials- LM2IMX280v2.1.xlsx, LM2IMX280v2.1.PDF
2016-12-16	HW-1.4*	Fixing of Ethernet LEDs	LM2IMX280v2.1.pdf LED_fix.pdf
2017-04-28	SW-2.0.0	See <i>Change_Log_spaceLYnk SW V2.0.0 & homeLYnk SW V2.0.0.pdf</i>	homeLYnk-2.0.0.img
2017-06-27	SW-2.0.1	See <i>Change_Log_spaceLYnk SW V2.0.1 & homeLYnk SW V2.0.1.pdf</i>	homeLYnk-2.0.1.img

* non-public documents